

Flange	Kapton	Fabricated	Tested	In Service	Out of Service	Comments
1	0.005"	12/01/2015			4/11/2018	Failed under vacuum
2	0.005"			06/2016		For He, N2
3	0.005"	Early 2016		04/11/2018		Current vacuum window
4	0.002"	Early 2016				Thinner material