

HIT CR a few times

	$DW = 1^4$	$u_2^4$	$u_3^4$	$u_4^4$
$b = 1^4$	$Rc = 100$			CR
$t = 2^4$	$Hc = 5$			
$o = 3^4$	$MS = 256$			
$i = 4^4$	$S1 = 2, 1$			
	$S2 = 3, 1$			
save	S			
	<del><math>PY = 1</math></del>			
	$EM = 2$			CR
	$PY = 1$			CR

HIT Ctrl-J several times  
(Motor is in Party-line mode)

Verify

$DW$	$\leftarrow$	<u>1</u>	Pr	$DW$	$\Delta J$
		<u>1</u>	Pr	MS	$\Delta J$
<u>save</u>		<u>1</u>	S		$\Delta J$