


# GIWAXS Exit Window Inventory 2021.06.14

Flange	Kapton	Fabricated	Tested	In Service	Out of Service	Comments
1	0.005"	6/3/2021	06/11/2021	06/14/2021		New regular window
2	0.005"			06/2016		For He, N2
3	0.005"	Early 2016		04/11/2018	06/14/2021	Current vacuum window
4	0.002"	Early 2016				Thinner material
5	0.005"	6/2021	06/11/2021			Backup window

This window



Flange 5 stored in cabinet in corridor office.  
Flange 2 stored in cabinet in corridor.

Flange 3: Ray will replace with new material